



U.S. Department
of Transportation
**Federal Aviation
Administration**

**Transport Airplane Directorate
Aircraft Certification Service**

1601 Lind Avenue Southwest
Renton, Washington 98057-3356

SEP 3 2010

In Reply
Refer To: 100S-GA-10-53

Mr. Kevin Torresdal
President
Davtron, Inc.
427 Hillcrest Way
Emerald Hills, CA 94062

Dear Mr. Torresdal:

This is in response to your letter dated August 24, 2010 regarding the installation of replacement clocks in small airplanes. We consider the installation of replacement clocks (including timers and stopwatches) in non-transport category airplanes to be minor changes in accordance with Title 14 Code of Federal Regulations (CFR) section (§) 21.93(a). Per CFR § 21.95, copies of this letter may be given to installing mechanics as evidence that this installation is considered minor. The installation should be documented using a maintenance log book entry referencing this letter.

If you have questions regarding any of the above issues, please contact me at telephone number (425) 917-6405, or by electronic mail at jeff.morfitt@faa.gov.

Sincerely,

Jeffrey A. Morfitt
Small Airplane Program Manager
Seattle Aircraft Certification Office